Carbon coater operation Procedure

Method 3 (Manual with pulse)